Work Ordo May-13-13 1:02		101470		*101	1470*						Page 1
Item ID: Revision ID: Item Name:	D3943-7			Accept	*N900	<b>040</b>	100	)* s	etup Stai	i Zi	S1*
Start Date: Required Date: Reference:	5/08/13 : 5/24/13	Start Qty: 20.00 Req'd Qty: 20.00	*20* *20*		Cust Item I Customer:	D:					
Approvals:		Plan: MUS	Date: 13-08-16	Tooling: SPC (Y/N):		ate:		R	tun Stai	171	R1* R2*
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr		Revision Nbr									
D3943		Е		•							~ ^ > -
*100 *100*		·		0.00	. 87	5.18	alara walka and	21	4		0A3 04 9-89
Hardinge Hardinge CNC Lath	ne Small	FOLIO REV DWG REV:									
		*****TAP	DRILL FOR 1/4"-20 IN C	ENTER OF PART****	***						
110		QC2- Inspect parts off m	achine FAI/FAIB	0.00	13.9	5-18		21	d		04 04 9-8
*110*, QC Quality Control		Мето		0.00		- · · ·					

										DQA	: Date	•
NCR: Y	es / No	•			<b>WORK ORDER NON-</b>	100	NFORM	MANCE / UP	DATE			
							<u>-</u> .			QA Closed	: Date	
Work Orde	eń:			<del></del>	DISPOSITION				AGAINST DE	PARTMENT	r/PROCESS	
Part N	<del>-</del> :	·	·····		Rework Scrap Use-as-is		ľ	Skid-tube Machining noforming	Crosstube Small Fab Finishing	4	Water Jet od. Eng. Coor. ore/Packaging	Engineering Quality Other
NCR N	lo			<del></del>	Work Order Update	]		Large Fab	Composite	]	Supplier	
Root				Descri	ption of work order update	П	nitial	Ac	tion	Sign &	Ī	
Cause	Date	Step	Qty		or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data												
Equip/Tooling		Ì		Ì								
Operator												İ
Material		-										
Setup						ļ						
Other			,									
Process												
Supplier												
Training							٠					
Unapproved											<u> </u>	
					F	AUL	T CATE	GORY				
Landi	ng Gear				General		-			_	_	_
	Bendin	g		<u> </u>	Bend		Grain			Ovalized	<u>_</u>	Pressure/Forced
	Centre	Not Conce	entric to	o/s	BOM/Route		Hardwa	re	<u> </u>	Over/Unde	r tolerance	Temperature/Cure
	Cracks				Broken/Damaged	L	Inspecti	ion Incomplete		Part Incorre	ect	Weld
	Crushe	d/Crimped			Burrs		Instruct	ions Incomplete/	Unclear	Part Lost/M	lissing	Wrong Stock Pulled
	Cuffs				Contamination		] Mainte	nance		Part Moved	·	
	Heat T	eat			Countersink		Mislabe	led		Positioned '	Wrong	
	Inspec	ion Strip ir	Tube		Cut Too Short		Misreac	i		Power Loss	/Surge	Other

Offset

Out of Calibration

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Torque Waves in Extrusion

Drill Holes

Drawing

Finish Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Ord  May-13-13 1:0		01470		*10	147	<b>N</b> *							Page 2	
Item ID: Revision ID: Item Name: Start Date: Required Date:	D3943-7 Stud 5/08/13 : 5/24/13	Start Qty: 20.00 Req'd Qty: 20.00	*20* *20*	Accept	C	900( ust Item II ustomer:		100	)*	Setup	Start Stop	IVI	S1* S2*	
Reference: Approvals:		lan:	Date:				te:	-		Run	Start Stop	"  \	R1*	
Sequence ID/ Work Center I 120 *120* QC Quality Control	D	Operation Description QC8- Inspect parts - seco	nd check	Set Up/ Run Hours 0.00	į	Tool ID 13/05/2	Tool #	Plan Code	Accep Qty 21	t Re Qt		Reject Number	Insp. Stamp OAS O8	
*130 *130* Packaging Packaging		Identify as per dwg & Sto	ock Location:	0.00							(	3/6/	32 (	ر اور ا
*140 *140* QC Quality Control		QC2!- Final Inspection -  Memo	Work Order Release	0.00		-	. 1		^	712 <u>-</u>	13-	mr 2	33	2

									DQA:	Date:	
NCR: Yes	/ No			WORK ORDER NO	N-CO	NFORN	MANCE / UPI		QA Closed:	Date:	
Work Order:				DISPOSITION				AGAINST DEI	PARTMENT	/PROCESS	
Part No.				Reworl Scrap Use-as-is Work Order Update	p s	Therm	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite		Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root				Description of work order upda	te	Initial	Act	ion	Sign &		
Cause	Date	Step	Qty	or Non-conformance	Ct	nief Eng	Descr	ription	Date	Verification	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other											

## Unapproved **FAULT CATEGORY Landing Gear** General Bend Ovalized Pressure/Forced Bending Grain Temperature/Cure BOM/Route Over/Under tolerance Centre Not Concentric to O/S Hardware Weld Broken/Damaged Part Incorrect Cracks Inspection Incomplete Wrong Stock Pulled Instructions Incomplete/Unclear Part Lost/Missing Crushed/Crimped Burrs Part Moved Cuffs Maintenance Contamination Countersink Mislabeled Positioned Wrong Heat Treat Power Loss/Surge Other Inspection Strip in Tube Cut Too Short Misread Offset Drill Holes Ripples in Bend Drawing Out of Calibration Torque Waves in Extrusion Finish Out of Sequence Turning Sequence Folio Outside Dimensions Wave/Twist in Tube

Process Supplier Training

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

May-13-13 1:02:24 PM

Work Order ID:

101470

Parent Item:

D3943-7

Parent Item Name:

Stud

**Start Date:** 5/08/13

Required Date: 5/24/13

**Start Qty: 20.00** 

Required Qty: 20.00

Comments:

Est Rev:A New Issue 09-06-03 JLM Verified By:EC IPP Rev:B as per dwg REV.C DD 10.02.22 verified by:EC IPP REV:C 11.08.16 AS PER REV.E DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M1010R0.375		Purchased	No			100	f	0.0000	0.02	0.421052			

ROUND BAR .375

112886

B.8.B

											DQA:	Date:	
NCR: Y	Yes	/ No				WORK ORDER NON-	CON	IFORM	MANCE / UF	PDATE			
					-						QA Closed:	Date:	
Work Orde	or.					DISPOSITION	ı			AGAINST DE	PARTMENT,	/PROCESS	
Part N	- No					Rework Scrap Use-as-is Work Order Update		! Thern	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite		Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
, terri					<del></del>	Work order opdate	-		20.80 . 02				
Root					Descri	ption of work order update	lt	nitial	Ad	ction	Sign &		
Cause		Date	Step	Qty	(	or Non-conformance	Chi	ief Eng	Des	cription	Date	Verification	QC Inspector
Doc/Data										i			
Equip/Tooling	Ц												
Operator	Ш												
Material	Ц												
Setup	Ш												,
Other	Ц		Ì		· ·	•					-		
Process	Ш												
Supplier	Ш			ļ			-						
Training	Щ												
Unapproved													
-:-							AUL	T CATE	GORY	<del></del>			
Landi		1			<u> </u>	General				_	1	<b>F</b>	1 .
		Bending			1	Bend	1 1	Grain			Ovalized		Pressure/Forced

BOM/Route Over/Under tolerance Temperature/Cure Centre Not Concentric to O/S Hardware Weld Part Incorrect Broken/Damaged Inspection Incomplete Cracks Wrong Stock Pulled Instructions Incomplete/Unclear Part Lost/Missing Crushed/Crimped Burrs Maintenance Part Moved Cuffs Contamination Positioned Wrong Countersink Mislabeled Heat Treat Misread Power Loss/Surge Other Inspection Strip in Tube Cut Too Short Ripples in Bend Drill Holes Offset Torque Waves in Extrusion Out of Calibration Drawing Out of Sequence Turning Sequence Finish Folio Outside Dimensions Wave/Twist in Tube

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

DART AEROSPACE LTD	Work Order:	101470
Description: Stud	Part Number:	D3943-7
Inspection Dwg: D3943 Rev: E		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.37	+/-0.030	. 366			EP. Sh	
0.25	+/-0.030	,245				
Ø0.201	+/-0.005	- 200				
				·		
· · · · · · · · · · · · · · · · · · ·						
					-	
						·
						•
•						

	7				
Measured by:	V.89	Audited by:	D.a. , DAS	Preliminary Approval:	
Date:	13-5-1F	Date:	13/05/21	Date:	

Rev	Date	Change	Revised by	Approved
_ A `	09.06.11	New Issue	KJ (A.	12/
В	12.05.15	Dimensions updated per Dwg Rev E	KJ OK	(1/11/
				7

